

#### Agenda

- Regional SW Program Updates
  - Illicit Discharge Detection and Elimination 2017 Update
     Watershed Partners Service Agreement

  - Plan Review
- Stormwater Master Plan
- Stormwater Inspection and Maintenance

  - Inspections and ActivitiesUrgent Storm Response ProcessLong-term Monitoring of Assets
- Stormwater Construction Plan
  - 2018 Projects

  - Permanent and Temporary Easement Policy
     Conservation Planning and Land Acquisition





#### Illicit Discharge Detection & Elimination

- What is community's role?
  - Title III and IV: sanitary overflows from any source, including illicit connections, are prohibited
  - Phase II MS<sub>4</sub> permit compliance



- Services provided by the District
  - BOH outfall screening/sampling for E. coli and flow
  - Assistance with source tracking through BOH and Water Quality and Industrial Surveillance group





### Illicit Discharge Detection & Elimination Summary of 2017 Sampling

- Outfalls Inspected = 4,148
- Outfalls with *E. coli* >10,000 MPN/100 mL = **140**
- Outfalls with flow >10,000 GPD = 65



## Illicit Discharge Detection & Elimination What to expect in 2018

- Notifications from NEORSD about problem outfalls
- Coordination meetings with community, NEORSD, and Ohio EPA
- Mapping update: Addition of outfalls in culverted streams
  - Cuyahoga County BOH to start with pilot community
  - More accurate MS<sub>4</sub> maps
  - Better data for source tracking





#### 2018 Central Lake Erie Basin Collaborative Services

Provide strategic implementation of the District's Regional Stormwater Management Program. Work includes:

- Development of a stormwater fee credit <u>assistance</u> program
- Development of a stormwater fee <u>tree</u> credit to compliment municipal & regional tree canopy recovery goals








#### 2018 Central Lake Erie Basin Collaborative Services


Provide strategic implementation of the District's Regional Stormwater Management Program. Work includes:


- Assist the District with the implementation of Stormwater Master Plan recommendations
- Assist Member Communities in updating parking lot and downspout disconnection codes


















# SW Master Plan Schedule

- Phase I: Indian Creek
  - Draft SWMP Recommendations
    - 1<sup>st</sup> Qtr 2018
- Phase II Watersheds
  - Brandywine, Chippewa, Tinkers
- Phase III & IV Watersheds
  - Furnace, Sagamore, Mud Brook, Yellow Creek, Cuyahoga River Tributaries (East and West)
  - Cuyahoga River Main Stem






# SW Master Plan Schedule


#### Phases II through IV:


- Draft Alternatives Development
  - Throughout 2018
- SWMP Recommendations
  - End of 2018













# SW Master Plan Community Communication • Meet with communities — Alternatives Evaluation • Recommendations and Community Report Your Watershed Team Leader serves as the point of contact between the communities and the District Northeast Ohio Regional Sewer District








- Asset Class Types:
  - Streams (Open)
  - Crossings (Bridges/Culverts)
  - Culverted Streams (Long Reaches of Buried Pipe)
  - Basins (Dry/Wet, Regulated/Unregulated)
  - Major Structures (Low Head Dams/Drop Structures/Locks)
- Acronyms:
  - ALR Acceptable Level of Risk
  - RSS Regional Stormwater System
  - BTU Building, Transportation, Utility Assets along the RSS
  - BEHI/NBS Bank Erosion Hazard Index/Near Bank Stress
  - SWSA Stormwater Service Area



























#### **SWIM Urgent Storm Response**

- Review any Advanced Warning Notification (e.g., National Weather Service)
- Field Check and Clean Known Problem Assets Prior to Storm
- Track Rainfall for Size of Storm (e.g., 10-yr, 24-hr) and Monitoring data for Evidence of Flooding (monitoring data)
- Review any media, customer, or Member Community reported flooding

Please notify us of any flooding along RSS!






#### **SWIM Urgent Storm Response**


- Field Check areas of concern, which can expand depending upon extent of flooding
- Conduct any recommended field maintenance activities, once water level permits safe access for Contractors
- Any observable structural issues are assessed.
   If a structural failure appears imminent, then both owner and senior District staff are notified for potential emergency declaration and resolution













#### SWIM 2018 Planned Activities


- Implement Recommended Maintenance Projects from SW Master Plans
- Continue Piloting Non-Routine Maintenance Projects
- Inspect and Inventory RSS assets and BTUs without condition scores
- Request Record Drawings from Member Communities (Basins and Crossings)


















2018 Stormwater Design						
Project Priority	Proposed Project Name	WAC Watershed	Subwatershed	Project Community	Highest BRE	Design NTP
1	Chippewa Creek_Bank Stabilization DS Rt 21 - CC00030 Chippewa Creek Bank Stabilization at Condominium- CC00032	Cuyahoga River South	Chippewa Creek	Brecksville	72	30-Jan-18 (2 Sites Combined
2	NEW SWIM Debris Racks, Access and Easements	Various	Various	Various	NA	26-Feb-18
3	Hemlock Creek and Mill Creek Bank Stabilization - HC00038, HC00040, HC00042, MC00125- Preliminary Design	Cuyahoga River North	Hemlock Creek	Seven Hills	69	1-Apr-19
4	Unnamed Trib. to E. Br. Rocky River Ridge Road Bank Erosion - RY00434 Baldwin Creek North Royalton Bank Erosion and Failing Private Crossing BD00291	Rocky River	Rocky River East Tribs Baldwin Creek	North Royalton	80	19-Apr-18 (2 Sites Combined
5	Unnamed Trib to Cuyahoga Failed Gabions CH00156	Cuyahoga River North	Cuyahoga River West Unnamed	Independence	61	29-May-18
6	Hemlock Creek Stream Erosion at HC00005	Cuyahoga River North	Hemlock Creek	Independence	69	29-May-18 (3 Site Combined)
	Cuyahoga River Erosion at BTU CY00103C_T001	Cuyahoga River North	Mainstem (west)	Independence	51	
	Cuyahoga River Left Bank Erosion near CVNP RR - CY00219	Cuyahoga River South	Mainstem (west)	Brecksville	50	
7	Pepper Luce Erosion and Deterioration - PC00145 Pepper Luce Gates Mills Blvd Culvert Deterioration PC00218	Chagrin River	Pepper Luce Creek	Pepper Pike	69	31-Jul-18 (2 Sites Combined
8	Big Creek West Branch Stabilization -WB00108, WB00072, WB00104	Cuyahoga River North	Big Creek	Parma	59	25-Jul-18
9	Chippewa Creek Erosion Near Local Sewer CC00170 Chippewa Creek Gabion Failure BTU CC00191_001 Chippewa Creek Bank Stabilization at SWM Facility - CC00082	Cuyahoga River South	Chippewa Creek	Broadview Heights	42	4th Qtr 2018 (3 Sites Combined







#### **Easement Policy**

Stormwater Construction Plan Projects

- Easements or permanent property rights will be required for all projects
- Owner compensation
  - Private Property owners may be paid for the easements based on fair market value established by appraisals
  - Member communities will not be compensated as outlined in the Service Agreements





#### **Easement Policy**

Inspection, Operation, Maintenance, and Monitoring

- No easement needed
  - Activities in ROW
  - Activities in an existing easement which can be assigned to the District
- Permanent easement installation of materials or facilities (i.e. stone)
- Right-of-Entry/temporary easement sufficient for most debris/sediment removal
- No compensation







