

Cuyahoga River -South

Regional Stormwater System in NEORSD Service Area



Regional Stormwater System not in NEORSD Service Area



Service Area



Community



Coordinate System: Ohio State Plane North Datum: NAD 1983, NAVD 1988

Projection: Lambert Conformal Conic

Sources: NEORSD GIS

Map Created: October 2017



This information is for display purposes only. The Northeast Ohio Regional Sewer District (NEORSD) makes no warranties, expressed or implied, with respect to the accuracy of and the useof this map for any specific purpose. This map was created to serve as base information for use in Geographic Information Systems (GIS) for a variety of planning and analysis purposes. The NEORSD expressly disclaims any liability that may result from the use of this map. For more information, please contact:NEORSD GIS Services, 3900 Euclid Avenue, Cleveland, Ohio 44115 (216) 881-6600 --- GIS@neorsd.org





Watershed Advisory Committee Cuyahoga River South October 2018







Agenda

- Sewer District Updates
 - Community Cost-Share
 - Local Sewer System Evaluation Studies
- Stormwater Master Plan
- Stormwater Inspection and Maintenance
 - Urgent Response Process
 - Problems to Projects
 - Community Meetings on Crossings and Culverts
- Stormwater Construction Plan
 - 2018 Project Updates
 - 2019 Annual SW Construction Plan Review
 - Construction Project Oversight





Community Cost-Share

• CCS Funds Balance (8/31/2018)

\$ 22,039,931

67 approved projects

\$ 9,150,615

17 approved allocation agreements

\$ 7,539,502

- CCS Funds available to Member Comm.
- \$ 5,349,814

30 of 55 Member Communities currently participating





Community Cost-Share Project Ideas

Examples of the Community Cost-Share Progam





The Community Cost-Share Program provides funding to Member Communities for Community-specific stormwater management projects. To implement the Community Cost-Share Program, the Northeast Ohlo Regional District (District) has formed a financial account termed "Community Cost-Share Account" for the aggregation and dissemination of funds derived from Stormwater Fee collected in each Member Community.

25% of the total annual Stormwater Fee collected in each Member Community is allocated to the Community Cost-Share Account for each Member Community. The Community Cost-Share Account is under the control of the District, with disbursement of funds to Member Communities through a grant application and reimbursement process, To access Community Cost-Share Program funds, Member Communities must maintain compliance with Title V: Stormwater Management Code. A Community Cost-Share Program Project must clearly promote or implement the goals and objectives of the District set forth in Title V and must be intended to address current or minimize new, stormwater flooding, erosion, and water quality problems.

More Information



■ Bedford



■ Bere





Broadview Heights


Brook Park

Brooklyn

Brooklyn Heights

Cleveland


Cleveland Heights








Local Sewer System Evaluation Studies






Stormwater Master Plan






Study Process








Stormwater Master Planning (status through September)








Cuyahoga River South SWMP



Total Study Area: **184,000** acres

- > 9 Subwatersheds
- 24 Member Communities

\$5.20 Million





Cuyahoga River South SWMP

Upcoming work

- Finalize:
 - SWMP WatershedReports
 - Community Reports
 - Data Deliverables,
 including models and
 inspection/assessment •
 data

Recommended Projects to Date

- Tinkers Creek15 Projects @ \$50.0M
- Chippewa Creek14 Projects @ \$55.7M
- Brandywine Creek
 19 Projects @ \$66.2M







Sam's Club – Brooklyn, Ohio – Big Creek Subwatershed

Problem:

- Stormwater inundation and impacts to Sam's Club, Brookpark Road & surrounding areas including fueling station
- Brookpark Road overtops around a 1-yr. storm
- Sam's Club parking lot begins to flood between the 2- and 5- yr storms
- Water enters the Sam's Club Building around the 10-yr storm








Problem Overview

- Sam's Club building & parcel site within both the 100-year FEMA & CRN SWMP model floodplains
- Total Drainage Area 8781 acres
- Percent Impervious 38% acres
- Problem Area Specific Target volume to manage for 100-year LOS 1,800 acre-feet or ≈1,361 football fields
- Watershed-wide: Target volume to manage for 100-yr LOS 3,300 acrefeet or 2,496 football fields






No upstream development at all

- All impervious area (development) removed
- Review 100-yr design storm (CRN SWMP parameter)
- Review depth at Sam's Club entrance 767.3

Results

 Inundation depth 1 ft above Sam's Club entrance elevation








Use open land areas –regardless of current ownership

- Review 100-yr design storm (CRN SWMP parameter)
- Review depth at Sam's Club entrance 767.3


Results

- Potential open area is about 440 acres
- Needed storage of 1,500 acre-ft exceeds potential
- Current watershed does not have enough open areas to address levels of flooding
- Available open areas at Walmart locations for storage opportunities can not remedy issues





Stormwater Master Plan Level of Service Evaluation – Mitigation Options



<2-year Scenarios</p>

- Current conditions (Do Nothing)
- Raise Brookpark Road
- Channel re-alignment south of Brookpark Rd
- Sam's Club/Walmart bridge removal

<5-year Scenario (New)

CSX crossing modification

<10-year Scenario</p>

Channel widening into Walmart parking lot

<25-year Scenario (New)</p>

 Channel widening into Walmart parking, CSX crossing upsizing & width increase at Brookpark Rd

Results:

- Increased floodplain storage from <2-yr to <25-yr LOS (up to <10-yr with channel widening only)
- Inundation depths reduced by about 1 inch at 100-yr
- Downstream problem areas show increase inundation depths



ITY OF BROADVIEW HEIGHTS AND CITY OF NORTH ROYALTON

PROJECT AREA CCPA09 A101, A102 & A103

Problem Statement

- One house has inundation at the foundation level starting in the 25-year design storm and first floor flooding starting in the 50-year design storm (CC00230, R010)
- One house has first floor flooding starting in the 50-year design storm (CC00230_B004)
- One house has inundation at the foundation level starting in the 50-year design storm and first floor flooding in the 100-year design storm (CC00230 B008)
- One house has inundation at the foundation level in the 10-year design storm and first floor flooding starting in the 50-year design storm (CC00230_B016)
- Three houses have inundation at the foundation level in the 10-year design storm and first floor flooding starting in the 25-year design storm (CC00230_B011, CC00230_B014 and CC00230_B017)
 Two roads (West Ridge Drive. CC00230_T018 and Echo Lane. CC00230_T019) are inundated but passable in the 10-year design storm, and
- become impassable (> 9" of water) in the 25-year design storm

 Two roads (Wallings Road, CC00183_T001 and Briarwood Drive, CC00184_T001) are inundated and impassable in the 10-year design storm
- and above

 One culverted stream (CC00183) has a hole with a visible, stream connectivity issues, and ongoing sedimentation issues

PROJECT LOCATION & EXISTING CONDITIONS









(B) Culverted stream CC00183 at inlet facing downstream

ITY OF BROADVIEW HEIGHTS AND CITY OF NORTH ROYALTON

PROJECT AREA CCPA09 A101, A102 & A103

Project ID	Project Elements	Known Constraints/
CCPA09_A101	Enlarge and deepen the basin at the north of Valley Lane Road and west of Ridge Drive from 1 to 2 acres (from 5 to 11 acre-feet of storage).	Requires cooperation cels. Some owned by Geotech and soil satisfies any contaminated soil
CCPA09_A102	Create 1,200 linear feet of channel restoration with connected floodplain along the north /south running open channel, acquire easements.	
CCPA09_A103	Demotish existing culverted stream; create 630 linear feet linear feet of channel resto- ration with connected floodplain	

rainct Paguite

for property interest on 25 par-

ity, some private owners.

are targeted for excavation

- Eliminated first-floor flooding in seven houses through the 100-year design storm (CC00230_B010, CC00230_B004)
- CC00230_B008, CC00230_B016, CC00230_B011, CC00230_B014 and CC00230_B017)
- Reduced flooding for four roads (West Ridge Drive, CC00230_T018; Echo Lane, CC00230_T019; Wallings Road, CC00183_T001 and Briarwood Drive, CC00184_T001)
- Demolished degraded culverted stream (CC00183) and restored channel; improving floodplain connectivity, stream function, and stream health
- Restored additional 1,200 linear feet of channel with connected floodplain; improving stream function and health as well as improving floodplain access
- . Expanded basin (CC00230) to increase storage; additional water quality volume further enhances stream function and health

Project Cost

\$12.852.000

*Costs do not include potential land acquisition unless noted

PROJECT ELEMENTS & RESULTS





CITY OF BROADVIEW HEIGHTS AND CITY OF NORTH ROYALTON


PROJECT AREA CCPA09_A101, A102 & A103

Problem Statement:

- One house has inundation at the foundation level starting in the 25-year design storm and first floor flooding starting in the 50-year design storm (CC00230_B010)
- One house has first floor flooding starting in the 50-year design storm (CC00230_B004)
- One house has inundation at the foundation level starting in the 50-year design storm and first floor flooding in the 100-year design storm (CC00230_B008)
- One house has inundation at the foundation level in the 10-year design storm and first floor flooding starting in the 50-year design storm (CC00230_B016)
- Three houses have inundation at the foundation level in the 10-year design storm and first floor flooding starting in the 25-year design storm (CC00230_B011, CC00230_B014 and CC00230_B017)
- Two roads (West Ridge Drive, CC00230_T018 and Echo Lane, CC00230_T019) are inundated but passable in the 10-year design storm, and become impassable (> 9" of water) in the 25-year design storm
- Two roads (Wallings Road, CC00183_T001 and Briarwood Drive, CC00184_T001) are inundated and impassable in the 10-year design storm and above
- One culverted stream (CC00183) has a hole with a visible, stream connectivity issues, and ongoing sedimentation issues

Northeast Ohio Regional Sewer District

PROJECT LOCATION & EXISTING CONDITIONS



2TY OF BROADVIEW HEIGHTS AND CITY OF NORTH ROYALTON

PROJECT AREA CCPA09 A101, A102 & A103

Problem Statement

- One house has inundation at the foundation level starting in the 25-year design storm and first floor flooding starting in the 50-year design storm (CC00230, R010).
- . One house has first floor flooding starting in the 50-year design storm (CC00230_B004)
- One house has inundation at the foundation level starting in the 50-year design storm and first floor flooding in the 100-year design storm (CC00230 B008)
- One house has inundation at the foundation level in the 10-year design storm and first floor flooding starting in the 50-year design storm
 (CC00230 R046)
- Three houses have inundation at the foundation level in the 10-year design storm and first floor flooding starting in the 25-year design storm (CC00230 B011, CC00230 B014 and CC00230 B017)
- Two roads (West Ridge Drive, CC00230_T018 and Echo Lane, CC00230_T019) are inundated but passable in the 10-year design storm, and become impassable (> 9° of water) in the 25-year design storm
- Two roads (Wallings Road, CC00183_T001 and Briarwood Drive, CC00184_T001) are inundated and impassable in the 10-year design storm and above
- One culverted stream (CC00183) has a hole with a visible, stream connectivity issues, and ongoing sedimentation issues

PROJECT LOCATION & EXISTING CONDITIONS





(A) View of open stream segment CC00194 bision fixing downstream (B) Culterfiel stream CC00183 at inlet facing downstream

CC00230_B008, CC00230_B016, CC00230_B011, CC00230_B014 and CC00230_B017) Reduced flooding for four roads (West Ridge Drive, CC00230_T018; Echo Lane, CC00230_T019; Wallings Road, CC00183_T001 and Briarwood Drive, CC00184 T001) Demolished degraded culverted stream (CC00183) and restored channel; improving floodplain connectivity, stream function, and Restored additional 1,200 linear feet of channel with connected floodplain; improving stream function and health as well as improving floodplain access Expanded basin (CC00230) to increase storage: additional water quality volume further enhances stream function and health **Project Cost** \$12.852.000 *Costs do not include potential land acquisition unless noted **PROJECT ELEMENTS & RESULTS**

· Requires cooperation for property interest on 25 par-

· Geotech and soil samples will be needed to identify if

cels. Some owned by city, some private owners.

any contaminated soils are targeted for excavation

PROJECT AREA CCPA09 A101, A102 & A103

Drive from 1 to 2 acres (from 5 to 11 acre-feet of storage).

north /south running open channel, acquire easements.

ration with connected floodplain

Enlarge and deepen the basin at the north of Valley Lane Road and west of Ridge

Create 1,200 linear feet of channel restoration with connected floodplain along the

Demolish existing a liverted stream; create 630 linear feet linear feet of channel resto-

Eliminated first-floor flooding in seven houses through the 100-year design storm (CC00230_B010, CC00230_B004.

CCPA09 A101

CCPA09_A102

CCPANS A103

CITY OF BROADVIEW HEIGHTS AND CITY OF NORTH ROYALTON

PROJECT AREA CCPA09_A101, A102 & A103

Project ID	Project Elements	
CCPA09_A101	Enlarge and deepen the basin at the north of Valley Lane Road and west of Ridge Drive from 1 to 2 acres (from 5 to 11 acre-feet of storage).	
CCPA09_A102	Create 1,200 linear feet of channel restoration with connected floodplain along the north /south running open channel, acquire easements.	
CCPA09_A103	Demolish existing culverted stream; create 630 linear feet linear feet of channel restoration with connected floodplain	

Known Constraints/Challenges:

- Requires cooperation for property interest on 25 parcels. Some owned by city, some private owners.
- Geotech and soil samples will be needed to identify if any contaminated soils are targeted for excavation.

Project Results

- Eliminated first-floor flooding in seven houses through the 100-year design storm (CC00230_B010, CC00230_B004, CC00230_B008, CC00230_B016, CC00230_B011, CC00230_B014 and CC00230_B017)
- Reduced flooding for four roads (West Ridge Drive, CC00230_T018; Echo Lane, CC00230_T019; Wallings Road, CC00183_T001 and Briarwood Drive, CC00184_T001)
- Demolished degraded culverted stream (CC00183) and restored channel; improving floodplain connectivity, stream function, and stream health
- Restored additional 1,200 linear feet of channel with connected floodplain; improving stream function and health as well as improving floodplain access
- Expanded basin (CC00230) to increase storage; additional water quality volume further enhances stream function and health

Project Cost


\$12,852,000

*Costs do not include potential land acquisition unless noted

Northeast Ohio Regional Sewer District

PROJECT ELEMENTS & RESULTS





Next Steps after Master Planning

Recommended Projects to Date

- Tinkers Creek15 Projects @ \$50.0M
- Chippewa Creek
 14 Projects @ \$55.7M
- Brandywine Creek
 19 Projects @ \$66.2M


Next Steps for Projects:

- Nomination to Construction Plan
 - Advanced Planning
 - Design
 - Design-Build
 - Property AcquisitionPrioritization
 - Phasing/Sequencing





Questions





Stormwater Inspection and Maintenance (SWIM)



SWIM Agenda

- Introduce SWIM Team Members
- Urgent Storm Event Response Process
- Small Scale Maintenance Projects
- Upcoming Community Meetings on Crossings





Westside SWIM Team

- Mark Link
 Supervisor
- Christina Silea
 Inspector
- Nikki Velez
 Inspector
- Claire Posius
 Project Coordinator
- Martina Jozanovic

 Data Maintenance

 Administrator

Eastside SWIM Team

- Keith McClintock
 Supervisor
- Jon Brauer
 Inspector
- Anne Roberto
 Inspector
- Mark Hornyak
 Project Coordinator
- Eric Baker

 Data Maintenance

 Administrator





SWIM Agenda

- Introduce SWIM Team Members
- Urgent Storm Event Response Process
- Small Scale Maintenance Projects
- Upcoming Community Meetings on Crossings





SWIM Progress Status

Urgent Storm Response Case Study April 15, 2018 Storm Event





SWIM Urgent Storm Event Response Process

- Review Advanced Warning Notifications
 - e.g., National Weather Service
- Field Check and Clean Known Problem Assets Prior to Storm
- Track Rainfall for Size of Storm (e.g., 10-yr, 24-hr) & Monitor Live Field Data for Evidence of Flooding
- Analyze Media, Customer & Member Community reported flooding





SWIM Urgent Storm Event Response Process

- Immediately Field Inspect Problem Assets Upon Receded Flooding
- Mobilize Contractors for Post-Storm Event Response Maintenance




Urgent Storm Event Response Case Study

April 15-16, 2018





Review of Advanced Warning Notifications




4/15/18 NWS **Notifications** received at 5:02 PM (Sunday) immediately prior to the storm



Sites SWIM Routinely Checks for Debris and Prior to Large Storms with Advanced Warning

SWIM routinely visits 21 sites for debris maintenance












Immediately Field Inspected Problem Assets Upon Receded Flooding



SWIM has a list of 42 known sites that are prone to flooding


Field inspected when reported heavy rainfall, high streams, or media reports of flooding in the area

Additional sites are added based on media reports or field observations





Mobilized Contractors to Perform Post-Storm Response Maintenance



79 site inspections

18 debris removal projects (many the same day as inspection)

Average yardage of debris was low compared to previous removals due to preventative maintenance



Rocky River: Rocky River East Branch

Member Community: North Royalton

Asset ID: RY00434


Maintenance Project: Debris Removal (10 CY)







Using Trail Cameras to Support the RSMP


















SWIM Agenda

- Introduce SWIM Team Members
- Urgent Storm Event Response Process
- Small Scale Maintenance Projects
- Upcoming Community Meetings on Crossings





Small Scale Maintenance Projects



21 small scale maintenance projects are underway as a pilot preventative maintenance program

- 11 Structural
 Maintenance projects
- 10 StreambankStabilization projects






Small Scale Maint Project: Streambank Stabilization Cuyahoga River South: Indian Creek



Small Scale Maint Project: Structural Repair Cuyahoga River South: Indian Creek



REPAIR OF PIPE UNDERMINING

NO SCALE

FIBER REINFORCED
CONCRETE LINING
EXISTING CMP
CULVERT
CULVERT
SUBGRADE

EXISTING CONCRETE

EXISTING CONCRETE

EXISTING CONCRETE

EXISTING CONCRETE

EXISTING CONCRETE

EXISTING CONCRETE
FINISHED SURFACE

EXISTING VOID
BELOW PIPE

CMP CULVERT INVERT


B
S

- Line invert to protect rusting CMP
- Provide structural concrete support in undermined area at outlet






Small Scale Maint Project: Streambank Stabilization Cuyahoga River South: Furnace Run



Small Scale Maint Project: Streambank Stabilzation Cuyahoga River South: Furnace Run

- Lay banks to a stable slope
- Install live branch layering and rock toe protection





SWIM Agenda

- Introduce SWIM Team Members
- Urgent Storm Event Response Process
- Small Scale Maintenance Projects
- Upcoming Community Meetings on Crossings





Upcoming Community Meetings to Discuss State of RSS Crossings

District Stormwater Service Area

2018 SWSA Structural Integrity Report Card	SWSA Subwatersheds
А	12
В	38
С	5
D	1
F	0
Total	56

The District continues to inspect RSS assets (55%)

Almost all RSS crossings have been inspected

Meetings will review SWIM findings and next steps for implementation and financing

- 327 SWSA RSS assets with Condition Rating = 4 or 5
- 63 SWSA RSS Crossing assets Condition Rating = 4 or 5





Upcoming Community Meetings to Discuss State of RSS Crossings

2018 Cuyahoga River South WAC Structural Integrity Report Card

RSS SUBTOTAL	904	406	<u>△</u> 45%	В	Δ	2.15	V	10.35
ASSET CLASS TYPE	RSS COUNT	COND SCORE COUNT	Percent Inspected	Report Card Grade (per structural integrity condition)		Average Structural Integrity Condition		AVG BRE
BASIN	21	11	<u>△</u> 52%	Α	\checkmark	1.4	4	9.5
CROSSING	308	205	√ 67%	В	Δ	2.1	Δ	12.9
CULVERTED_STREAM	25	14	<u>△</u> 56%	B+	Δ	1.9	Δ	15.9
Major Structure	3	_	0%					
STREAM	547	176	32 %	B-	Δ	2.3	4	7.0

- 68 CRS RSS assets with Condition Rating = 4 or 5
- 15 CRS RSS Crossing assets with Condition Rating = 4 or 5















Cuyahoga River South



Cuyahoga River South








Cuyahoga River South Watershed Construction

Sioux Lane Culvert Replacement in Macedonia







Sioux Lane Culvert Replacement


Before Construction: existing 6 corrugated metal culvert pipes

After: New structure restores flow capacity and improves maintenance by reducing debris build-up










CHIPPEWA CREEK BANK STABILIZATION AT ROUTE 21

Brecksville, Ohio



SUMMARY

The project will address erosion issues along the left bank of Chippewa Creek that threatens structural integrity of a commercial building.

This stabilization project is necessary to help realign the stream away from the high bank and protect the building from potential damage.

CUYAHOGA RIVER SOUTH WATERSHED

CHIPPEWA CREEK SUBWATERSHED



Project Details

Asset Number: CC00030

Contract Type: GES/Bid/Build

Construction Cost: \$1,500,000


Anticipated Construction NTP: 1st QTR 2020

Watershed Team Leader: WebbR@neorsd.org



Northeast Ohio Regional Sewer District

Stormwater Design & Construction Program



New Design and Construction Projects Cuyahoga River South


				Project	Total
	Proposed Project Name	RSS Asset ID(s)	Subwatershed	Community	BRE
		BR00003, BR00004,		Sagamore Hills	
1	Lower Brandywine Creek Stabilization in Sgamore Hills Twp	BR00008	Brandywine Creek	Township	72
		BA00015, BA00016,			
2	Bear Creek Culvert Removal in North Randall	BA00017	Bear Creek	North Randall	67
	Brandywine Creek - Owen Brown Bridge Replacement in				
3	Hudson	BR00261	Brandywine Creek	Hudson	32
		CC00231, CC00230,		Broadview	
4	Chippewa - Broadview Hts Echo Lane Flooding Project	CC00184, CC00183	Chippewa Creek	Heights	32
		IC00303, IC00302,			
		IC00301, IC00300,			
		IC00299, IC00298,			
5	Indian Creek - Bedford/Ledge	IC00088, IC00087	Indian Creek	Macedonia	27
		IC00072, IC00073,			
		IC00074, IC00075,			
6	Indian Creek - Valley View/E Aurora	IC00076	Indian Creek	Macedonia	27
7	Indian - Bank Stabilization U/S Bluejay	IC00060	Indian Creek	Macedonia	25
		BR00110, BR00112,			
		BR00113, BR00114,			
8	Brandywine - E Highland Restoration	BR00116, BR00118	Brandywine Creek	Macedonia	24
	Brandywine Creek - Barlow Community Center Dam	BR00281, BR00282,			
9	Improvements	BR00283, BR00284	Brandywine Creek	Hudson	13





NEORSD Stormwater Design & Construction Program

Cuyahoga River South Watershed



Project Delivery Methods

- GES- Bid-Build
- Design-Bid-Build
- Design-Build
- Small Scale Projects
 - -Under \$50K
 - -\$50K-\$250K





Multi-Site Streambank Stabilization







Metrics of Success

- 9,336 LF of Stream Restored/Stabilized
- 23,725 Tons of Sediment Removed
- 6.6 Acres of Floodplain Reconnected
- 575 LF of Culverts Repaired/Replaced
- Property Interests Obtained
 - 2 Fee Simple Acquisitions (18 acres)
 - 17 Permanent Easements Acquired






Beecher's Brook Bank Stabilization























CHANNEL EVOLUTION MODEL (SIX STAGES) Simon and Hupp, 1986


Class I. Sinuous, Premodified h<hc




Class II. Channelized* h<hc




Class III. Degradation h<hc




Class IV. Degradation and Widening h>hc



Class V. Aggradation and Widening h>hc




Class VI. Quasi Equilibrium



*Anthropogenic




















































What's Next

- District Stream Restoration Site Visit
 - October 25 (Thursday) from 2 to 3 pm
 - Meet at 6700 Beta Drive, Mayfield OH, 44143
- Annual WAC Representative Designation – January 2019
- Next WAC Meeting March 2019





Questions

Rachel Webb 216-881-6600 Ext. 6645 webbr@neorsd.org

Donna Friedman 216-881-6600 Ext. 6768 friedmand@neorsd.org



Stormwater Program: Community Resources
http://www.neorsd.org/communitystormwaterresources.php



